AKS50-50

- Connector from Al conductor to Cu conductor.
- Stranded/solid Al conductors, stranded/multistranded Cu conductors.
- For multi-stranded Cu conductors, contact crimping using the Dual system is recommended.
- Two crimps are required for AI, normally one for Cu.


AlCu through connector, from Al conductor to Cu conductor. For stranded AI cable 50 mm², or for solid Al cable 70 mm², to stranded/multi-stranded Cu cable 50 mm². When crimping the Cu section, place the dies between the mark on the sleeve and the edge of the Cu section. Used with Elpress certified systems V1300, V250.











s1 (mm): 23 d (mm): 9.6 D (mm): 20 L (mm): **75.5** s (mm): 45 d1 (mm): 11 D1 (mm): 14.5

AWG/MCM Stranded Al: 1/0 AWG AWG/MCM Solid Al: 20 AWG AWG/MCM Cu: 1/0 AWG mm² Stranded AI: 50 mm² Solid Al: 70

mm² Cu: **50**

Screen conductor (mm²): 57

