AKS35-10S

- Transition joints from stranded Al conductors to solid Cu conductors 10 mm² (e.g. Excel, Excelett).
- Two crimps are needed for both Al and Cu.

AlCu through connector, from Al conductor to Cu conductor for stranded Al cable 35 mm², or for solid Al cable 50 mm², to solid Cu cable 10 mm². When hexagonal crimping Cu conductors, the dies are placed in the middle between the marking groove and the outer edge. Used with Elpress certified systems V1300, V250.









Item number: 7333-407200 EAN: **7393487020658**

s1 (mm): 33 d (mm): 8.5 D (mm): 20 L (mm): **86** s (mm): 45 d1 (mm): 4.5 D1 (mm): 7

AWG/MCM Stranded Al: 2 AWG AWG/MCM Solid Al: 10 AWG AWG/MCM Cu: 8 AWG mm² Stranded Al: 35 mm² Solid Al: 50 mm² Cu: 10